

1/25








FIG. 1



. Sandania






FIG. 4b






FIG 4c



first first that that it ofto that made at what that that that that that that

FIG. 5








FIG. 6b










FIG. 8

DIGITIZED MAGNETIC SENSOR READING








FIG. 11a




FIG. 11b




FIG. 12a






FIG. 12b



15/25







FIG. 15



<u>FIG. 16a</u>







FIG. 16b











FIG. 18






FIG. 20





FIG. 21



No

606

Match?

Accept Bill

Yes

Suspect Code:

Magnetic/Optical Mismatch

FIG. 23




FIG. 24